# Oil Field Environmental Incident Summary

**Responsible Party:** Oxy USA Inc **Well Operator:** OXY USA INC.

Well Name: DAKOTA MEYER 1-19-18H-143-97

Field Name: CROOKED CREEK Well File #: 26357

Date Incident:2/20/2014Time Incident:1500Facility ID Number:County:DUNNTwp:143Rng:97Sec:19Qtr:

Location Description: Oil was released out of the flare and impacted the land adjacent to location,

Submitted By: Dustin Tescher Received By:

Contact Person: Dustin Tescher

5 GREENWAY PLAZA STE 110 HOUSTON, TX 77046-0506

General Land Use: Pasture Affected Medium: Topsoil

Distance Nearest Occupied Building:1.25 MilesDistance Nearest Water Well:1.25 Miles

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

	Spilled	Units	Recovered	Units
Oil	10	gallons	0	barrels
Brine	0	barrels	0	barrels
Other	0	barrels	0	barrels

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 5/6/2014 Clean Up Concluded: 4/15/2014

Risk Evaluation:

Flammable material on the surface material

Areal Extent:

Followup

0.25

**Units** 

barrels

## Potential Environmental Impacts:

Contaminated surface material

#### Action Taken or Planned:

The contaminated surface material will be removed and taken to disposal.

Wastes Disposal Location: TBD

Agencies Involved:

## **Updates**

Date: 2/21/2014 Status: Reviewed - Follow-up Required Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

Date: 3/3/2014 Status: Inspection Author: Martin, Russell

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

## Notes:

3/3/2014 at 17:07 on location. Impact to northeast of flare pit off location. Area adjacent to well pad has been dug up due to recent pipeline installation, and dirt shows staining. Further from well pad is pasture land with recent evidence of cattle; grass is impacted. Fence row further to northeast shows light staining. Phone call to report contact on cleanup operations. According to contact, employee managing cleanup quit the company last Friday. Report contact will call back with update on plans for the site.

Date: 7/29/2014 Status: Correspondence Author: Martin, Russell

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

Phone call with report contact. According to personnel handling cleanup, incident was cleaned up once snow had melted from site.

Date: 9/29/2014 Status: Inspection Author: Martin, Russell

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

## Notes:

9/29/2014 at 18:14, on location. New growth visible in scraped pipeline row; vegetation adjacent to wellpad does not have visible staining.